### HITACHI AIR CONDITIONING PRODUCTS PHIL'S. INC.

1238 Edsa Balintawak Quezon City

# PRODUCT FIELD INSPECTION REPORT

approved:

BARRIENTOS 2010 11-14. ARIEI prepared:
PAMINIANO
MIZ 11- 14.
JAMES

Report no: PFIR-12-030	Pass / distributed to: (HAPP-M)		
Company and Address	7-11 MONTALBAN BURGOS, J.P. RIZAL COR. MONTAÑA DRIVE, BRGY. BURGOS MONTALBAN, RIZAL		
Subject:	THE UNIT WAS TRIPPED OFF AFTER FEW HOURS OPERATION		
Model and Serial no:	RAM-6FNS (E01867,E01978)		
Checked / inspected: (Hitachi Representative)	ENGR. JAMES ROLAND PAMINIANO / REGIENALD VILLON	Date of Inspection	November 13, 2012
		Service Reg. No.	20112

**Problem reported** 

The unit was unable to operate due to protection device activated.

#### Actual Problem based on Inspection :

## 1. Why the unit was frequent tripping?

One of the possible cause is the activation of protection device, the display are P5 and P9. The meaning of P5 is Discharge Gas


Temperature Increase Protection and P9 is Unbalance Power


Source Detecting. You can see at picture#3, the actual installation of power supply wire and transmission wire. Based on hitachi manual, the power supply wire and transmission wire must be separated because it can create an induction thru the wire and that's why the protection device is activated. The power supply for indoor unit must have a separate circuit breaker.


At picture #1, the actual location of outdoor unit. The middle outdoor unit have the alarm P5. In that case, there's no enough fresh air to sucked by the outdoor unit.



## ACTUAL LOCATION OF OUDOOR UNIT







### STANDARD INSTALLATION SPACE

## TERMINAL BLOCK OF OUTDOOR UNIT

### SOLUTION / REMARKS

- 1. Separate the power supply of indoor unit.
- 2. Separate the transmission wire to the power supply.
- 3. If P5 still occur, the standard installation space must be applied.